DPW ADPW PWS STP, GLM

CITY OF MOUNTAIN VIEW

SFUND RECORDS CTR 2807-91854

SFUND RECORDS CTR 88172026

Public Works

Ameico
Circo
Elmat
Fairchild Semiconductor
Hewlett-Packard
Industrial Research
Micro Science Associates
Pacific Press Publishing Assn.
Raytheon
Spectra Physics
Sylvania

Movember 13, 1967

Union Carbide

Vidar.

Mr. Ed Routhier, Plant Engineer Union Carbide Corporation 365 Middlefield Road Mountain View, California

Doar Mr. Routhler:

We wish to express our appreciation for your cooperation in reducing our sewago treatment operating problems.

Since starting our intensive industrial waste sampling and testing program a year ago we have found progressively better performance on the part of waste dischargers. We feel that this change in performance results from an increased awareness of the significance of departures from acceptable limits of waste quality.

It has been interesting to discover the predominant factors contributing to lack of satisfactory pH control. These can be described as follows.

increased production or new processes overloading neutralizing facilities.

Lack of awareness of the reason or need for control within reasonable limits.

Inadequate or poorly maintained control and alarm systems.

Human failures in maintenance.

It is gratifying to report that each major contributor of industrial wastes has improved plant controls and maintenance, or is in the process of so doing, to better meet the City's waste quality standards. These are tangible results of management's willingness to cooperate in resolving a problem.

We look forward to the time when our surveillance program serves primarily to warn of impending equipment or control malfunction of an industrial waste discharger rather than to gauge performance.

Sincerely,

GLM:cm

GEORGE L. McPHEETERS Water Division Engineer